

Table 14.6

Uncured	Cured	Cured and coated
1.186	1.145	1.138
1.184	1.152	1.129
1.183	1.151	1.144
1.206	1.162	1.13
1.208	1.174	1.172

Average	1.1934	1.1568	1.1426
D	0.012482	0.011389	0.01754423

test for uncured and cured	0.000123	Significant difference
test for uncured and cured and coated	0.002059	Significant difference
test for cured and cured and coated	0.066981	Not significant difference

-test looks for significant difference between two sets of data

-value Want a p value smaller than the critical value 0.05
 Indicates there is >95% chance that the data difference is significant