



8/27/2019.
Alex Stocum.



Internal section of screw may be hollow all way through - or just where 2nd thread.

no foot to push Ampule end.

"external thread" "Stinger"



Internal Threads to engage Stinger.