


**REMARKS**

Fig. 4 has been amended to change the label below reference number 118 from what appears to be "IIF Oscillator" to "HF Oscillator." It appears to Applicant's representative that a photocopying error caused this lack of clarity in Fig. 4 as originally filed. Support for the amendment to Fig. 4 can be found at at least page 17, lines 11-15 of the specification as originally filed. It is believed that entering this amendment does not require further search or consideration, and that no new matter is presented.

Respectfully submitted,

JENKENS & GILCHRIST,  
A Professional Corporation



Michael W. Maddox  
Reg. No. 47,764

1445 Ross Avenue, Suite 3200  
Dallas, Texas 75202-2799  
(214) 855-4614  
(214) 855-4300 (fax)